AnsellGUARDIAN® CASE STUDY: MACHINERY & EQUIPMENT

A POPULAR MOTOR HOME MANUFACTURER



BACKGROUND

This RV manufacturer is based in North America and its vehicles are used primarily in leisure travel and outdoor recreation activities. They have a large assembly facility that is surrounded by smaller satellite plants with over 2,000 employees that work over three shifts.

STRENGTHENED END USER RELATIONSHIP



IMPROVED SAFETY



OBJECTIVES

- Reduce the number of cut injuries
- Increase PPE compliance
- Reduce the amount of SKU's

ANSELL GUARDIAN® SOLUTIONS

The manufacturer's main concern was the number of cut injuries being sustained in production. Ansell GUARDIAN[®] deduced this was due to lack of safety compliance and non-usage of gloves. In conjunction with their safety group it was decided to move to a minimum of a cut level A2 platform. The company also needed a glove that could be used if workers moved from department to department and the best glove for this was the **HyFlex[®] 11-644**. In addition, the **HyFlex[®] 11-93**1 was also chosen as it could be used with adhesives and because it reduced puncturing due to its reinforced thumb crotch.

RESULTS

- 100% compliance!
- Reduction in SKU's by approximately 50%
- Three different glove styles (replaced by the HyFlex® 11-644)
- Significant cut injury reduction




HyFlex[®] 11-644

- Enhanced cut protection with a high level of dexterity
- Longer wear due to low palm weight
- Excellent abrasion resistance



HyFlex® 11-931
Ultra-lightweight for enhanced comfort and dexterity
Safe handling in dry-to-oily applications
Reinforced thumb crotch for





Corporate Headquaters: 111 Wood Avenue, Suite 210, Iselin, NJ 08830 Phone: + 732-345-5400 www.ansell.com/services [®] and [™] are trademarks owned by Ansell Limited or one of its affiliates. © 2019 All Rights Reserved.